ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	8	Kodigehalli
Street ID	**Street Name**	**Significant Landmark**
W0274	2nd Crs, Maheshwari Nagar	SC COLONY AT Maruthinagara and BB nagar
Segment No.	**Total Length (m)**	
8/S-W0274/S110856	160.45	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	160.45	77.579613	13.058950	77.581005	13.058460	W0375	DEAD END

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to roads and drain SC COLONY AT Maruthinagara and BB nagar in Ward no 8 (Kodigehalli) Kodigehalli Sub-Division Yelahanka zone	1380000	2016
Year	**Type of Work**	**Other Work Type**
2016 - 2017	Asphalting	
Tender	**Work Details**	**Job No. / Work Code**
Not a Tender	Improvements to roads and drain SC COLONY AT Maruthinagara and BB nagar in Ward no 8 (Kodigehalli) Kodigehalli Sub-Division Yelahanka zone	008-16-000041
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/ EE/BTP/WO/99/2016-17	05/08/2016	90 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
05/08/2016	04/08/2017	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
KRIDL BANGALORE		0.00
Phone No.	**E-Mail ID**	
9449863065		

Field Inspection Details

Number of Trees	Any Other Information	Name
0		SRINIVASA MURTHY

Date of Inspection	Remarks
25/11/2016	COMPLETED

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	25/11/2016	25/12/2016	COMPLETED
SE	VASU K M	25/11/2016	25/12/2016	COMPLETED
EE	YARAPPA REDDY	25/11/2016	25/12/2016	COMPLETED
AEE	RAJANIKANTH MALLI	25/11/2016	25/12/2016	COMPLETED
AE	SRINIVAS MURTHY	25/11/2016	25/12/2016	COMPLETED
AE	SRINIVAS MURTHY	25/11/2016	25/12/2016	COMPLETED